


FIG.I



be advantageously adjusted according to one or more parameters. In a particularly preferred but Figure 2. The proportional representation of a plurality of components in a working sample may non-limiting aspect, recovery limits (dashed lined) are applied to achieve either a normalized sample or alternatively a sample in which targeted components are selectively enriched.